



Pt 100 ohm
Temp. probe
(Optional)

2 wires

Temperature (Pt 100 ohm) TRANSMITTER

Model : TR-TMP2W

Features	2 wires, both for signal and power supply.
Measure Range	-100 °C to 400 °C
Output	4 - 20 mA -100 °C = 4 mA 0 °C = 7.2 mA 400 °C = 20 mA
External Adjustment	ZERO VR SPAN VR
Power Supply	9 - 30 DCV
Operation Temperature	0 - 50 °C 32 - 122 °F
Operation Humidity	Less than 80 %RH
Accessory Included	Pt 100 ohm probe is optional.
Optional Accessories	Pt 100 ohm temperature probe : TP-100 TP-100A
Mounting	Din rail or Wall, socket is included.
Case	ABS plastic
Others	Four wires connection

